# Hand welding extruder HSK18 RSX /HSK18 RFX



#### **BASIC EXTRUDER**

- Extrusion welding from PEHD, PP, PVC and PVDF\*
- temperature probe, location in the melt chamber
- rod feeding, no additional gearing
- Permanent speed control
- Control units for actual / desired mass and air temperature
- Cold start protection
- Rod diameter 3 and 4 mm
- 1 pce nozzle blank included

\*PVDF with special screw

#### **TECHNICAL DATA**

Output 1.8 kg/h (with PEHD rod 4 mm)

Heating extruder 500 W / air 2200 W

Drive 750 W
Air requirement 300 l/min.
Voltage 230 V / 50Hz

Weight 5,3 kg

Guarantee screw and cylinder 24 months

## **HSK18 RSX (WITH HOT AIR BLOWER)**

- Works as basic extruder, without external air supply
- Hot air blower controlled (air quantity 300 l/min)
- Technical data see basic extruder
- Heating hot air blower 2200 W

### **ADDITIONAL EQUIPMENT**

Welding nozzles
 Transportation box
 Extruder nozzle preheating
 Prolongation
 Angle adaptor
 Air compactor

Welding rod Widen

Technical execution subject to modifications